



MATERIAL SAFETY DATA SHEET

**SUBJECT : UPS F. 210
SUPER S CLEANER**

Manufactures by : WESTERS INDUSTRIES, PT
Jl. Industri Selatan 10 Blok EE No. 11B Jababeka industrial
District **Cikarang – Indonesia**
Emergency call : [6221-89841382](tel:6221-89841382)
Website : www.westers-ind.com
Email : info@westers-ind.com

Page 1 of 3

A. PHYSICAL DATA :

- Boiling point (760 mm Hg) : Above 392° F (200° C)
- Solubility : Pos
- Specific gravity (25° C) : > 1
- Vapor density : > 1
- Freezing point : > 1
- Evaporation rate : > 1
- Appearance : Blue Odorless Caustic Liquid
- Odor : Acid
- Vapor pressure : Less +
- % Volatile by volume : 80%

B. HAZARDOUS DATA :

Component	Weight %(appr)	TLV in ppm
- SIGMET	1 – 35	-
- Surfactant	1 – 10	-
- Sodium	1 – 5	-
- Sodium Hydroxide	10	-

C. FIRE & EXPLOSION HAZARDS :

- Flash point : N.A
- Extinguishing media : N.A
- Unusual fire and explosion : N.A
- Flammability in air : N.A

E. REACTIVITY :

- Stability : Stable
- Conditions to avoid : N.A
- Materials to avoid (Incompatibility) : N.A
- Hazardous decomposition products : N.A



MATERIAL SAFETY DATA SHEET

**SUBJECT : UPS F. 210
SUPER S CLEANER**

Manufactures by : WESTERS INDUSTRIES, PT
Jl. Industri Selatan 10 Blok EE No. 11B Jababeka industrial
District **Cikarang – Indonesia**
Emergency call : [6221-89841382](tel:6221-89841382)
Website : www.westers-ind.com
Email : info@westers-ind.com

Page 2 of 3

F. TOXICITY & FIRST AID :

- Medical condition aggravated : In case of over exposure seek medical
By exposure attention immediately
- Effects of acute toxicity : N.A
- Swallowing : May result in nausea, vomiting, breathing
Difficulties and weakness and also may
Result in kidney damage by ingestion of
Large quantities of the product.
- Inhalation : high vapor concentration may result in
Dizziness, headache etc. expose to fresh
Air.
- Skin contact : Warm skin immediately with plenty of
Water and apply soap and flush with
Plenty of water until the effect is subsided
In case of severity contact a physician.
- Eye contact : Remove from the exposure immediately
& flush with plenty of water for 15
minutes until irritation is subsided . in
case of severity contact a physician.
- Notes to physician : There is no specific antidote.
Treatment of overexposure should be
Directed at the control of symptoms and
Clinical conditions.

G. SPILL OR LEAK PROCEDURES

- Steps to be taken if material is spilled – wear suitable protective equipment. Small spills should be flushed with large quantities of water large spills should be collected for disposal.

H. SPECIAL PERSONAL PROTECTION

- Respiratory : Use air respiratory, facial masks etc.
- Ventilation : Local exhaust is adequate
- Skin protection : Aprons, gloves made of P.E or
Neoprene rubber
- Eyes protection : safety glasses are recommended
- Other protection equipment : N.A



MATERIAL SAFETY DATA SHEET

**SUBJECT : UPS F. 210
SUPER S CLEANER**

Manufactures by : WESTERS INDUSTRIES, PT
Jl. Industri Selatan 10 Blok EE No. 11B Jababeka industrial
District **Cikarang – Indonesia**
Emergency call : [6221-89841382](tel:6221-89841382)
Website : www.westers-ind.com
Email : info@westers-ind.com

Page 3 of 3

I. SPECIAL PRECAUTIONS

- Precautions to be taken during handling or storage – Warning! Harmful if inhaled or absorbed. May cause dizziness and drowsiness. Don't inhale vapors. Use in adequate ventilated areas. Accidental contact should be washed immediately with plenty of water.

G. WASTE DISPOSAL METHOD

- Incinerate in a furnace where permitted under appropriate federal, state and local regulations.

H. REGULATORY INFORMATION.

- STATUS ON SUBSTANCE LISTS
Comprehensive Environmental Response Compensation and liability Act of 1989 (CERCLA) requires notification of the National Response Center of Release of quantities of Hazardous substance equal to or greater than the reportable quantities(RQ s) in 40 CFR 302.4.