



MATERIAL SAFETY DATA SHEET

Manufactures by : WESTERS INDUSTRIES, PT
Jl. Industri Selatan 10 Blok EE No. 11B Jababeka industrial
District **Cikarang – Indonesia**
Emergency call : [6221-89841382](tel:6221-89841382)
Website : www.westers-ind.com
Email : info@westers-ind.com

**SUBJECT : UPS F. 812D
SOLVENT DEGREASER**

Page 1 of 2

A. PRODUCT DESCRIPTION :

UPS F. 812D is a near neutral green transparent liquid indicated for use wherever there is a need to remove heavy deposits of mineral oils and greases from hard surfaces.

B. APPLICATION :

UPS F. 812D has general application throughout general industry, transport, marine and the mining industry. Some specific use are – in site cleaning of car and truck engines, degreasing of all automotive component such as sumps, gear boxes and other transmission components, removal of oil, grease and oily carbon from engine blocks, cylinder heads and overhead gear, removal of oil and impacted soils from suspension components, cleaning of concrete floors.

C. FEATURES & BENEFITS :

1. Rapidly penetrates and dissolve oil and grease, and even oily carbon.
2. No heating of solution is necessary to obtain maximum performance
Characteristic.
3. Does not contain chlorinated solvents.
4. Suitable for use on all common metals.
5. Provides spectacular cleaning results when applied by either spray, brush or swab
Methods, or when used by immersion.
6. Combined solvent / surface system eliminated need for two operations to remove
Mixtures of oily soils and light films of dry soils (dirts, dust and swart)
7. Rinses freely from sound paint work, leaving gloss unimpaired.

D. CHEMICAL & PHYSICAL PROPERTIES :

Form	: Liquid
Color	: Green
Flash point	: 762 ° C
Specific Gravity	: 0.81
Freezing Point	: Below –17 ° C
Residue	: None



MATERIAL SAFETY DATA SHEET

**SUBJECT : UPS F. 812D
SOLVENT DEGREASER**

Manufactures by : WESTERS INDUSTRIES, PT
Jl. Industri Selatan 10 Blok EE No. 11B Jababeka industrial
District **Cikarang – Indonesia**
Emergency call : [6221-89841382](tel:6221-89841382)
Website : www.westers-ind.com
Email : info@westers-ind.com

Page 2 of 2

E. METHOD OF USE :

UPS F. 812D is used as received.

1. Low Pressure Spray :
Fill spray unit undiluted UPS F. 812D and apply to the surface to be cleaned.
Allow a well time of up to 15 minutes then either blow moisture of with an air
Hose or rinse with fresh water.
2. Low Pressure Spray:
Place articles to be cleaned in the undiluted UPS F. 812D. Allow parts to soak
Until soil can be easily removed by either wiping, blowing full with air or flushing
With fresh water.
3. Brush or Wipe :
Using undiluted UPS F. 812D brush or wipe the article to be cleaned. Remove
Excess solution or loosened soil by blowing off wit air or rinsing with fresh water.

F. SAFETY DATA

EYES : If contact lenses are worn, remove immediately and flush with
Water for at least 15 minutes.

SKIN : Avoid prolonged contact with skin. In use wear cotton gloves.

Keep out of mouth and avoid prolonged breathing of its vapors.

If poisoning occurs, contact poisons information center or a doctor.